



### PURCHASE REQUEST

**Entity Name:** Philippine Fiber Industry Development Authority

**Fund Cluster** 101

<b>Office/Section:</b>		PR No.: 18-07-451 Responsibility Center Code:	Date: 07-16-18		
Stock/Property No.	Unit	Item Description	Quantity	Unit Cost	Total Cost
XXXXXXXXXXXXXXXXXX	XXXX	Supply of labor and materials for the repair and replacement of defective One (1) set of Brake rotor disc; and brakepads (front - left and right) One (1) set Brakedrum and brakeshoe (rear - left & right) of Toyota Land Cruiser with Plate No. SFY-413 Original brake rotor disc, front (right & left)..... P30,000.00 Original brakepads, front (right & left).....8,000.00 Original brake drum, rear (right & left).....P33,000.00 Original brakeshoe, rear (right & left)..... 6,500.00 Labor..... 2,500.00 <b>TOTAL P80,000.00</b>	XXXXXXXXXX	XXXXXXXXXX	XXXXXXXXXX
		<b>Total P80,000.00</b>			
		Charge to FUTD Fund			



Purpose: For FUTD laboratory use. (For Toyota Land Cruiser with Plate No. SFY-413)

	<b>Requested by:</b>	<b>Approved by:</b>
<b>Signature</b>		
<b>Printed Name</b>	REMEDIOS V. ABGONA, PhD	PETRONILO B. JABAY
<b>Designation</b>	Chief, FUTD	OIC- Deputy Executive Director