Appendix 60

## PURCHASE REQUEST

Office/Section: FUTD		PR No.: 24-05-443 Responsibility Center Code:		<b>Date:</b> May 20, 2024		
Stock/Property No.	Unit	Item Description		Quantity	Unit Cost	Total Cost
XXXXXXXXXX	Lot	Preventive maintenance Detection and Alarm Syster Processing and Utilization I located at BAI Compound Avenue, Bgy. Vasra, Dilima City Scope of Works:  1. Dismantling and cle the units 2. Re-tightening, and wiring and connection 3. Funtionality and audi 4. Replacement of 2 pcs xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	Laboratory I, Visayas In, Quezon  eaning of  inspect Ins bility test Batteries	1 XXXXXXX	XXXXXXXXX TOTAL	P 35,000.00  XXXXXXXXXXX  P35,000.00
MEVELUPASENT AUVILE SCY PALOFFICE SPICE AND A. ARDS COMM	BUTY	Charge to EV2022 ELITO I I		Purchase F Budget is v	olthin: Fu	DAMMATTEE  DC - 4-93  TO  Island
Purpose: For FP		ding maintenance and fire dete				
Signatura	Reque	sted by:	Approved by:			
Signature Printed Name	CO	CHUNKÝN		/ "/		
Designation Designation	-	ONCEPCION D. JOCSON Officer-in-Charge, FUTD		OIC, Deputy Executive Director		