




# PURCHASE REQUEST

Entity Name: PHILIPPINE FIBER INDUSTRY DEVELOPMENT AUTHORITY, RO V Fund: \_\_\_\_\_  
 Cluster: Research Unit

<b>Office/Section:</b>		<b>PR No.</b> JD-2025 B-02	<b>Date:</b> February 7, 2025		
		<b>Responsibility Center Code:</b>			
Stock/Property No.	Unit	Item Description	Quantity	Unit Cost	Total Cost
	Job Order	Providing labor and materials for the repair of the roof and roof frame of the administrative building and cottage at the Sorsogon Fiber Experiment Station (SFES), San Juan, Casiguran, Sorsogon	1	P479,000	P479,000
		1. Mobilization/Demobilization & Removal of Existing Roof and Wooden Trusses and Purlins			
		2. Installation of Trusses, Purlins and G.I Roof (Part A: Electrical)			
		3. Installation of Trusses, Purlins and G.I Roof (Part B: Roofing Works)			
		4. Welding Works (Please see attached POW and DUPA for detailed specifications.)			
		Requested by:			
		 ABMER O. PATRICIO SFES In Charge			
		<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: 0 auto;">                     BAC                      RECEIVED: 9/1                      DATE: 2/11/25                 </div>			
			<b>TOTAL</b>		

**Purpose:** To protect the building from weather and ensure the safety of personnel, materials, and equipment at the Sorsogon Fiber Experiment Station in San Juan, Casiguran, Sorsogon.

<b>Requested by:</b>		<b>Approved by:</b>	
Signature			
Printed Name	<b>IRMA M. NAVARRO</b>		<b>MARY ANNE R. MOLINA</b>
Designation	Research Unit Head		OIC-Regional Director